

39. SCHEDULE 1 - DESCRIPTION OF SPA FACILITY


The Spa Facility will include all the facilities and infrastructure within the designated 'exclusive use' area in the Skukuza Camp in the Kruger National Park.

39.1 Facility

39.1.1 Facility within the Skukuza Camp in the Kruger National Park consisting of the following:

- 39.1.1.1 Two steam rooms and changing facilities (One male and one female)
- 39.1.1.2 Two single bed massage rooms
- 39.1.1.3 One twin bed massage room
- 39.1.1.4 Two shower and change room facilities (One male one female)
- 39.1.1.5 Paraplegic toilet
- 39.1.1.6 Female toilet facility
- 39.1.1.7 Male toilet facility
- 39.1.1.8 Reception and refreshment bar area
- 39.1.1.9 Hairdressing and manicure area (Internal) can also include pedicures
- 39.1.1.10 Outside veranda and relaxation area (uncovered at present)
- 39.1.1.11 Access to existing swimming pool facility (public and non-exclusive)

The following aerial photo outlines the location of the Spa facility within the Skukuza Main Camp within the Kruger National Park:



Aerial Photo 1: Skukuza Spa Facility

The following outlines the floor plan for the Skukuza Spa Facility:

